

EXHIBIT E – Documentation Indicating WTC 7 Steel Shipped to NIST

NIST Steel Photos-Final.pdf - Adobe Reader

File Edit View Window Help

178 / 625 102%

Tools Sign Comment

fig-16.jpg	688 KB	6/25/2003 07:49:02 AM
fig-17.jpg	2017 KB	11/26/2003 04:02:40 PM
fig-18.jpg	882 KB	7/31/2003 09:26:00 AM
fig-19.jpg	1305 KB	11/26/2003 05:53:12 PM
fig-19.orig.jpg	898 KB	7/31/2003 10:43:22 AM
fig-20.jpg	677 KB	6/25/2003 07:35:32 AM
fig-21.bmp	1345 KB	11/26/2003 11:02:48 AM
fig-22.alternate-1.jpg	771 KB	6/25/2003 01:15:28 PM
fig-22.alternate-2.jpg	831 KB	7/31/2003 02:09:58 PM
fig-22.jpg	750 KB	6/25/2003 01:15:18 PM

Total 33 file(s); Size: 26764672 Byte(s)

e:\wtc-foia\banovic\wje\reports\final 12-10-03\figures-lowres

__fig-00.cover.jpg	185 KB	9/8/2003 02:20:24 PM
__fig-01.jpg	186 KB	9/17/2003 09:06:36 AM
__fig-02.jpg	77 KB	9/17/2003 09:03:36 AM
__fig-03.jpg	85 KB	9/17/2003 09:05:38 AM
__fig-04.jpg	185 KB	9/8/2003 02:20:24 PM
__fig-06-weld-haz.jpg	83 KB	6/27/2003 10:08:40 AM
__fig-07-weld-tear-s-10.jpg	42 KB	6/27/2003 10:41:02 AM
__fig-08-weld-impact-m-2.jpg	179 KB	9/17/2003 09:01:48 AM
__fig-09-weld-fire-s-10.jpg	199 KB	9/17/2003 09:18:10 AM
__fig-10-weld-pinch-c-40.jpg	192 KB	9/17/2003 09:12:10 AM
__fig-11-bend-m-2.jpg	168 KB	9/17/2003 03:20:52 PM
__fig-12-ribbons-m-2.jpg	120 KB	9/17/2003 03:46:30 PM
__fig-13-severed-m-30.jpg	136 KB	11/25/2003 01:02:14 PM
__fig-14-ribbons-m-27.jpg	84 KB	9/17/2003 04:03:12 PM
__fig-15-fire-s-10.jpg	233 KB	9/17/2003 10:16:26 PM
__fig-16-fire-m-4.jpg	159 KB	9/17/2003 10:22:16 PM
__fig-17-fire-k-2.jpg	184 KB	9/17/2003 10:41:22 PM
__fig-18-joists-far.jpg	249 KB	9/18/2003 09:10:30 PM
__fig-19-joists-close.jpg	232 KB	9/18/2003 09:06:12 PM
__fig-20-wtc7-overall.jpg	144 KB	9/18/2003 09:17:40 PM
__fig-22-k-1.jpg	121 KB	9/18/2003 09:28:18 PM
__fig-22-k-1-alt-1.jpg	127 KB	11/26/2003 12:28:12 AM
__fig-22-k-1-alt-2.jpg	129 KB	11/26/2003 12:36:16 AM
__fig-xx-unused.jpg	144 KB	9/17/2003 09:46:02 AM


Total 24 file(s); Size: 3742959 Byte(s)

Find wtc7 Previous Next

In Support of Task 2 under Project 3 of the NIST WTCI
Visual Observations of the Steel Recovered From the World Trade Center Site



Figure 20. General view of several pieces believed to have been recovered from structures other than WTC 1 and WTC 2



Coming into parking lot



Bldg 205 Area

- WTC2 identified exterior perimeter column
- Unidentified exterior perimeter column
- Unidentified core material
- Material believed to be from WTC7
- Material with markings/stampings not identified